Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080095-9

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2961-E. COLORADO ST., PASADENA 8, CALIF.

No 127859

RECEIVED FROM: Collins-Powell Co.

DATE RECD 12-18-56

P. O. NO. 3041

VENDOR PACKING SLIP NO. 6657

CHARGE TO: NOT

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R

ACCT. OR W. O. NO.

S. O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
100	#8-32 NC90° Anchor Nut MSNA #22NA27-58-02 730180-32 (322-000000-10007-0-0-00-00-32)	100	✓	
100	#10-32-NF2 Anchor Nut MSNA #22NA27-1-02 730180-47 (322-000000-10100-0-0-00-00-02)	100	✓	
100	#10-32 NF2 Corner Nut-MSNA 22NA 5-02 #730180-K 48 (322-000000-10101-0-0-00-00-02)	100	✓	
100	Right L Bracket #10-32-MSNA 22NA27-2-02 730180-72 (322-000000-10102-0-0-00-00-02)	100	✓	
100	#10-32 Anchor Nut Two Lug KM MSNA 22NA21-28-02 730180-50 (322-000000-10201-0-0-00-00-02)	100	✓	

RECEIVED BY: [illegible]

INSPECTED BY: [illegible]

DATE 1/31/57

REJECTS RETURNED ON SHIP. MEMO NO.

HYCON MFG. COMPANY

2961-E. COLORADO ST., PASADENA 8, CALIF.

No 127860

RECEIVED FROM: Collins-Powell Co.

DATE RECD 12-18-56

P. O. NO. [illegible] 3567

VENDOR PACKING SLIP NO.

CHARGE TO: NOT

CONTRACT CODE NO.	DRAWING NUMBER	DWG. DASH OR STANDARD PART NO.	DWG. REV.	LOT NO.	CLASS NUMBER	OPER. NUMBER	BUY OUT CODE NO.	O R

ACCT. OR W. O. NO.

S. O. NO.

QUANTITY RECEIVED	DRAWING NO. AND DESCRIPTION	QUANTITY ACCEPTED	QUANTITY REJECTED	REMARKS
100	1/4 x 28 Anchor Nut MSNA 22 A21-22-048 730188-51 (322-000000-10202-0-0-00-00-32)	100	✓	

RECEIVED BY: [illegible]

INSPECTED BY: [illegible]

DATE 1/31/57

ON SHIP. MEMO NO.

Approved For Release 2000/04/18 : CIA-RDP81B00879R000500080095-9